


X650 Voluntary Recall

SCUBAPRO is conducting a voluntary recall of the X650 second stage regulator. A manufacturing error could cause the main housing of some regulators to change shape over time, and the cover and diaphragm to become dislodged. If this occurs, air flow will be interrupted and the regulator will no longer function.

Only X650 second stage regulators purchased from authorized Scubapro dealers from November 2004 through May 2006, are affected by this recall. You can determine if you have one of these units by looking for a visible raised bump located on the right side of the regulator between the letter "C" and where the mouthpiece attaches to the regulator body.



At Scubapro, safety comes first and we ask that you stop using the X650 second stage regulator immediately.

Replacement Program

SCUBAPRO will replace your X650 regulator with a new one within thirty (30) days or sooner if your regulator is found to be one of those affected by this recall. In order to obtain a replacement, send an email with the required information below. After we obtain your name, address, and telephone number, Scubapro will send you a return shipping box and UPS shipping label. All you will need to do is to place the X650 regulator in this box, seal the box, attach the UPS label, and drop it off at any UPS shipping location. Once we have received your regulator, we will begin processing your replacement order.

To contact SCUBAPRO UWATEC, please send your email to recallinfo@scubapro.com and include the following information:

- Name
- Address
- Phone number where you can be reached